

Interim Reclamation and Stormwater Inspection

April 11, 2018

Operator: SRC ENERGY INC- #10311

Location ID: 434391

Inspection Document #: 682403479

Weld County, CO

SENW Section 4 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Kelly Farms
Location ID: 434391



Photo 1. Photo taken from the western location, facing West. Russian thistle weed debris observed throughout portions of the location.



Photo 2. Photo taken from the southwest location, facing East. See comments under Photo 1. In addition, there does not appear to be sufficient perennial vegetation along the south-facing slope along the southern location.

Inspection Photos
Location Name: Kelly Farms
Location ID: 434391



Photo 3. Photo taken from the southern location, facing Southeast. See comments under Photo 1 and 2.



Photo 4. Photo taken from the southeast location, facing East. See comments under Photo 1. There is little to no perennial establishment along the southeast and eastern portions of the location.

Inspection Photos
Location Name: Kelly Farms
Location ID: 434391



Photo 5. Photo taken from the southeastern location, facing South. Photo illustrates Russian thistle weed debris that has blown off location.

Inspection Photos
Location Name: Kelly Farms
Location ID: 434391



Photo 6. Photo taken east of the location, facing West. The fill north and east fill slopes have not been stabilized. Erosion blanket netting no longer in proper functioning condition.

Inspection Photos
Location Name: Kelly Farms
Location ID: 434391



Photo 7. Photo taken east of the location, facing South. Photo illustrates the southeast fill slopes has not been stabilized.

Inspection Photos
Location Name: Kelly Farms
Location ID: 434391



Photo 8. Photo taken from the southeast location, facing Northeast. Unused equipment needs to be removed per Rule 603.f.