

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2018

Submitted Date:

04/09/2018

Document Number:

690100417**FIELD INSPECTION FORM**Loc ID 320426 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Brown, Devin	(303)-349-0302	dbrown@petrosharecorp.com	
Lloyd, Bill		blloyd@petrosharecorp.com	
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203732	WELL	SI	04/01/2017	GW	001-09292	WYMAN 34-6	EG

General Comment:

Followup inspection conducted in response to FIR doc #690100364 dated 02/02/2018; Actions Required identified during this inspection have been completed. This well has been plugged and abandoned.

Note: The Actions Required outlined on ENV inspection doc #688500028 submitted 3/20/18 must be completed as outlined; AR details outlined in the environmental section of this report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Action Required Completed; Unused unmarked flowline risers have been removed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 203732 Type: WELL API Number: 001-09292 Status: SI Insp. Status: EG**Flowline**

#1	Type:	of Lines	
----	-------	----------	--

Flowline Description

Flowline Type: Size: Material:
Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment:

Corrective Action:

Date:

Environmental**Spill/Remediation:**

Comment: Partially-buried produced water vessel removed sometime between 02/02/2018 & 03/16/2018 (see attached photo log) without prior approval of a Form 27 Site Investigation & Remediation Work Plan.

Corrective Action: Submit Form 27 as required by Rule 905.b. Retroactive corrective action deadline reflects the last date of a COGCC time-stamped photo of the vessel.

Date: 02/02/2018

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401601858	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428391