

Inspection Photos

API: 05-067-06571

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Date: 3/21/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is comprised of a mix of desirable grasses such as smooth brome (*Bromus inermis*) and weeds such as yellow tumbled mustard (*Sysimbrium altissimum*).



Photo 3. View of the northern portion of the interim reclamation area from the northeastern corner facing westward. What appears to be surface owner equipment is stored in the interim reclamation area.



Photo 4. View of the southern portion of the project area from the southwestern corner facing eastward. Surface owner equipment is also stored in the southern portion of the interim reclamation area.



Photo 5. Rig anchor needs marker or removal.