

Inspection Photos
Location Name: Hooze-Bjolin #1
Location ID: 318942



Photo 1: Location, looking SE



Photo 2: Wellhead, looking N

Inspection Photos
Location Name: Hooze-Bjolin #1
Location ID: 318942



Photo from prior inspection for comparison



Photo 3: Stained soil removed

Inspection Photos
Location Name: Hooze-Bjolin #1
Location ID: 318942



Photo from prior inspection for comparison



Photo 4: Treater removed

Inspection Photos
Location Name: Hooze-Bjolin #1
Location ID: 318942




Photo from prior inspection for comparison



Photo 4: Incorrect sign at pump jack

Inspection Photos
Location Name: Hooze-Bjolin #1
Location ID: 318942



Photo from prior inspection for comparison



Photo 5: Stained soil remediated

Inspection Photos
Location Name: Hooze-Bjolin #1
Location ID: 318942



Photo from prior inspection for comparison



Photo 6: Stained soil at engine

Inspection Photos
Location Name: Hoozee-Bjolin #1
Location ID: 318942




Photo from prior inspection for comparison



Photo 7: Emergency number did not receive response.

Inspection Photos
Location Name: Hooze-Bjolin #1
Location ID: 318942



Photo from prior inspection for comparison



Photo 8: Production tanks labeled.

Inspection Photos
Location Name: Hooze-Bjolin #1
Location ID: 318942



Photo from prior inspection for comparison



Photo 9: Stained soil removed.

Inspection Photos
Location Name: Hooze-Bjolin #1
Location ID: 318942



Photo from prior inspection for comparison



Photo 10: Stained soil removed.

Inspection Photos
Location Name: Hooze-Bjolin #1
Location ID: 318942



Photo from prior inspection for comparison



Photo 11: Oil taken off pit. Stained soil in bottom of pit.