

Inspection Photos
Location Name: Mais #1-35
Location ID: 330881



Photo 1: Location, looking SW



Photo 2: Wellhead, looking W

Inspection Photos
Location Name: Mais #1-35
Location ID: 330881



Photo from prior inspection for comparison



Photo 3: Weeds at lease road controlled.

Inspection Photos
Location Name: Mais #1-35
Location ID: 330881



Photo from prior inspection for comparison



Photo 4: Weeds controlled at treater

Inspection Photos
Location Name: Mais #1-35
Location ID: 330881



Photo from prior inspection for comparison



Photo 5: Deadmen marked.

Inspection Photos
Location Name: Mais #1-35
Location ID: 330881



Photo from prior inspection for comparison



Photo 6: Stormwater erosion mitigated, weeds controlled

Inspection Photos
Location Name: Mais #1-35
Location ID: 330881



Photo from prior inspection for comparison



Photo 7: Stormwater erosion mitigated.

Inspection Photos
Location Name: Mais #1-35
Location ID: 330881



Photo 8: In use, plugged flowline riser.