

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/18/2018

Submitted Date:

04/18/2018

Document Number:

684905322

**FIELD INSPECTION FORM**

Loc ID 330881 Inspector Name: Pesicka, Conor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 70385  
Name of Operator: SMITH ENERGY CORP  
Address: 12706 SHILOH RD  
City: GREELEY State: CO Zip: 80631

**Findings:**

17 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Chris	303-709-6157	smithenergy@live.com	VP; North operations
Smith, Glenn	(970) 381-6253	gsmithten@what-wire.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256249	WELL	PR	05/03/2015	GW	123-19817	MAIS 1-35	PR
268127	PIT	AC	06/02/2003		-	MAIS 1-35	AC

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

WEEDS

Comment: [Weeds controlled.](#)

Corrective Action:

Date:

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type SEPARATOR

Comment: [barbed wire](#)

Corrective Action:

Date:

Type SEPARATOR

Comment: [agricultural](#)

Corrective Action:

Date:

Type TANK BATTERY

Comment: [barbed wire](#)

Corrective Action:

Date:

Type PIT

Comment: [barbed wire](#)

Corrective Action:

Date:

Type WELLHEAD

Comment: [agricultural](#)

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 0

Comment: [Misattributed on prior inspection. Inventory correction.](#)

Corrective Action:

Date:

Type: Horizontal Heater Treater

# 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors

# 2

Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	Deadmen marked		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	Bull plugged riser marked in use.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	Open Top		40.615740,-103.617490
Comment:	Steel grid on top				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared with crude oil			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	200 BBLS	STEEL AST		40.615740,-103.617490
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Berms repaired.				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 256249 Type: WELL API Number: 123-19817 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR intermittently.

Corrective Action:

Date:

**BradenHead**

Comment: Bradenhead not plumbed to surface.

Corrective Action:

Date:

Facility ID: 268127 Type: PIT API Number: - Status: AC Insp. Status: AC

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: [Stormwater erosion mitigated.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 268127      Lat: 40.615720      Long: -103.617600

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type: Livestock      Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:

Anchor Trench Present: NO      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: [Produced water pit, permitted.](#)

Corrective Action

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
684905325	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4438413">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4438413</a>