

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/31/2018

Submitted Date:

04/19/2018

Document Number:

685100453**FIELD INSPECTION FORM**

Loc ID 312970	Inspector Name: NEIDEL, KRIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 1 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested															
Operator Information: OGCC Operator Number: <u>10407</u> Name of Operator: <u>ANTLER ENERGY LLC</u> Address: <u>PO BOX 104</u> City: <u>BAGGS</u> State: <u>WY</u> Zip: <u>82321</u>																			
Contact Information: <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Clay, Evans</td> <td></td> <td>clayevans@yahoo.com</td> <td></td> </tr> </table>					Contact Name	Phone	Email	Comment	Clay, Evans		clayevans@yahoo.com								
Contact Name	Phone	Email	Comment																
Clay, Evans		clayevans@yahoo.com																	
Inspected Facilities: <table border="1"> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> <tr> <td>223077</td> <td>WELL</td> <td>PR</td> <td>07/31/2003</td> <td>OW</td> <td>081-06439</td> <td>AMOCO-FEDERAL 21-1</td> <td>EI</td> </tr> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	223077	WELL	PR	07/31/2003	OW	081-06439	AMOCO-FEDERAL 21-1	EI
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status												
223077	WELL	PR	07/31/2003	OW	081-06439	AMOCO-FEDERAL 21-1	EI												

General Comment: <p>On January 31, 2018 COGCC Environmental staff inspected well 081-06439. This was an Environmental Inspection, please assure that corrective actions from previous inspection have been addressed. This inspection does not excuse previous Corrective Actions. The weather was overcast, snow covered and 20 degrees. The well was SI at the time of inspection. It appeared that no snow maintenance was being done on the location. There is 2 pits on location; 1 Pit is inside the tank battery, pit was covered in snow, netting was in disrepair. The second pit was North of the wellhead, no net, no liner. The COGCC database shows only 1 pit related with this well, 112982. By 5/14/2018 please provide an update to kris.neidel@state.co.us on the status of these pits. Netting on pits should be maintained in good working order prior to use of pit.</p>							
---	--	--	--	--	--	--	--

Inspected FacilitiesFacility ID: 223077 Type: WELL API Number: 081-06439 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100454	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4439859