

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/31/2018

Submitted Date:

04/19/2018

Document Number:

685100455

FIELD INSPECTION FORM

Loc ID 312863 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10407
Name of Operator: ANTLER ENERGY LLC
Address: PO BOX 104
City: BAGGS State: WY Zip: 82321

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Clay, Evans		clayevans@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222661	WELL	PR	06/01/2015	GW	081-06021	FEDERAL-CHAMBERLIN 22-1	EI

General Comment:

On January 31, 2018 COGCC Environmental staff inspected well 081-06021. This was an Environmental Inspection, please assure that corrective actions from previous inspection have been addressed. This inspection does not excuse previous Corrective Actions. The weather was overcast, snow covered and 20 degrees. The well was SI at the time of inspection. No pit was photographed during the inspection. Attached is an aerial that shows a potential pit. The COGCC database show 2 pits related with this well, 100416,116617. By 5/14/2018 please provide an update to kris.neidel@state.co.us on the status of these two pits.

Inspected Facilities

Facility ID: 222661 Type: WELL API Number: 081-06021 Status: PR Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100456	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4439860