

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/31/2018

Submitted Date:

04/19/2018

Document Number:

685100459**FIELD INSPECTION FORM**
 Loc ID 311769 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10407Name of Operator: ANTLER ENERGY LLCAddress: PO BOX 104City: BAGGS State: WY Zip: 82321**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Clay, Evans		clayevans@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223134	WELL	PR	10/01/2015	OW	081-06496	KLAENHAMMER 3-A	EI

General Comment:

On January 31, 2018 COGCC Environmental staff inspected well 081-06496. This was an Environmental Inspection, please assure that corrective actions from previous inspection have been addressed. This inspection does not excuse previous Corrective Actions. The weather was overcast, snow covered and 20 degrees. The well was SI at the time of inspection. It appeared that no snow maintenance was being done on the location. No pit was photographed during the inspection. Attached is an aerial that shows a potential pit. The COGCC database shows 1 pit related with this well, 100413. By 5/14/2018 please provide an update to kris.neidel@state.co.us on the status of this pit.

Inspected FacilitiesFacility ID: 223134 Type: WELL API Number: 081-06496 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100461	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4439873