

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401615557  
Date Received:  
04/20/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Amato, Joe

719-845-2110

josephamato@tcenergy.us

Fitzgerald, Edie

719-845-2108

ediefitzgerald@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102760

Inspection Date: 03/08/2018

FIR Submit Date: 03/23/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 307510

Location Name: GOLDEN EAGLE-633S67W Number: 28NWSW County: LAS ANIMAS

Qtrqr: NWS Sec: 28 Twp: 33S Range: 67W Meridian: 6  
W

Latitude: 37.142401 Longitude: -104.899002

FACILITY - API Number: 05-071- -00 Facility ID: 217763

Facility Name: GOLDEN EAGLE Number: 28-12 (SD-1)

Qtrqr: NWS Sec: 28 Twp: 33S Range: 67W Meridian: 6  
W

Latitude: 37.142401 Longitude: -104.899002

CORRECTIVE ACTIIONS:

1 CA# 115193

Corrective Action: Remove Debris from Location.

Date: 04/30/2018

Response: CA COMPLETED

Date of Completion: 04/19/2018

Operator Comment: The location sign, all pipe line risers, roof anchors, concrete chunk and rebar have all been removed from location. See attachment for details.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 115194

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 04/30/2018

Response: CA COMPLETED

Date of Completion: 04/19/2018

Operator  
Comment:

The stormwater conveyance ditch between the well pad and New Elk Coal Mine rail road right of way has been swelled out to avoid a "V" shaped channel. Rip rap was place in the channel for soil stablization. The pad was re-contoured to match the surrounding terrain. The earth disturbance was hydro-seeded. See attachment for details.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Debris removal, erosion control, re-contour and seeded all earth disturbances. See attachment for details.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

Title: SR Environmental Tech.

Date: 4/20/2018 1:59:31 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

401615575	Debris removal, erosion control and seeding
-----------	---------------------------------------------

Total Attach: 1 Files