

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/18/2018

Submitted Date:

04/20/2018

Document Number:

691300116

FIELD INSPECTION FORM

Loc ID 323357 Inspector Name: Kraich, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10261
Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLC
Address: 730 17TH ST STE 500
City: DENVER State: CO Zip: 80202

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|--------------------------|---|
| , | | cogccinspection@pdce.com | ALL INSPECTIONS |
| Kraich, Adam | 970-420-0536 | Adam.Kraich@state.co.us | (Area 117) Field Operations |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 245108 | WELL | SI | 08/01/2017 | OW | 123-12903 | PAULINE 5 | SI |

General Comment:

(This area is currently blank for general comments.)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Wellhead shows Pauline 5-8 | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|-------|--|
| Comment: | <input type="text"/> | Date: | |
| Corrective Action: | <input type="text"/> | | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|---------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Red Iron | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | 4 strand wire | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | # | | corrective date |
|-----------------------------|----------|-------|-----------------|
| Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Horizontal Heated Separator | # 1 | | |
| Comment: | Anchored | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|----------|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | <50 BBLS | FIBERGLASS AST | | , |
| Comment: | Anchored | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

| Berms | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Venting: | | | |
|--------------------|--|--|-------|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Flaring: | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 245108 Type: WELL API Number: 123-12903 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

| Comment | User | Date |
|--|---------|------------|
| Well recently aquired by PDC from bayswater. See document #401485748 | kraicha | 04/20/2018 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 691300117 | Inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4440854 |