

Inspection Photos 04/17/18
Location: UPRR 43 PAN AM I #23
API # 05-123-09055



Wellhead and signage; View looking West



Leaking flowline valve and stained soils

Inspection Photos 04/17/18
Location: UPRR 43 PAN AM I #23
API # 05-123-09055



Misc trash and unused equipment on location



Unused pipe barrier on west side of location

Inspection Photos 04/17/18
Location: UPRR 43 PAN AM I #23
API # 05-123-09055



Trash/ unused electric wire and conduit requiring removal



Trash and unused equipment on location (view east)