

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/17/2018

Submitted Date:

04/23/2018

Document Number:

690100459

FIELD INSPECTION FORM

Loc ID 318749 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: K P KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Lara-Mesa, Susana		cogcc@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242099	WELL	PR	08/01/2017	GW	123-09890	UPRR 43 PAN AM I 30	EG

General Comment:

[COGCC Engineering Integrity staff is waiting on the final submittal of flowline NTO data for this well \(submittal of satisfactory flowline pressure test completed\). Details in the flowline section of this report. Photos uploaded can be accessed via link at end of report.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash observed on location that includes unused electrical conduit and wire, unused pipe/ concrete debris and a plastic tarp on the south side of well pad.		
Corrective Action:	Comply with COGCC Rule 603.f; Remove trash from well pad.	Date:	05/23/2018
Type	UNUSED EQUIPMENT		
Comment:	Unused steel pipe barrier (painted yellow) observed on the southwest corner of well pad		
Corrective Action:	Remove unused equipment per 603.f	Date:	05/23/2018

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#		corrective date
Flow Line			
Comment:	Stained soils observed where flowline turns into ground from wellhead; the riser and valve/ bullplug are leaking.		
Corrective Action:	Repair equipment/ flowline riser (valve); Clean up stained soils in the area of release.	Date:	05/23/2018

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 242099 Type: WELL API Number: 123-09890 Status: PR Insp. Status: EG

Flowline

#1	Type: Non-Well Site	1 of Lines
----	---------------------	------------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents: Multiphase

Integrity Summary

Failures: Spills: Repairs Made: No
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Fail Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Based on communications between KPK and COGCC Engineering Integrity staff, the offsite flowline associated with this well has failed a recent pressure test. The well is currently shut in (at wellhead/ valves need to be LOTO at wellhead).

 Note: As soon as possible, provide COGCC Integrity staff with a tentative schedule for 1) Identifying the point(s) of failure on the flowline 2) repairing flowline or abandoning/ replacing the flowline 3) completing follow-up flowline pressure testing.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100473	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4442366