

**Inspection Photo**  
**Clough RMV 240-29**  
**API# 045-07486**  
**Inspection # 689300946**



**Location photo # 1**



**Photo #2 Access road needs repaired**