

Caerus D09A Pad
API 045 17758
Spill/Release Point ID #454721 (Flowline Spill)



Looking south. Excavated area on the left, near wellheads



Looking east. Area excavated with hydrovac. Pipeline corridor with multiple pipelines difficult excavation.

Caerus D09A Pad
API 045 17758
Spill/Release Point ID #454721 (Flowline Spill)



Pipeline has been repaired. Initial samples indicated some HC impact remaining. Excavation was expanded and sampling was repeated. Samples currently in the lab.



Water at the bottom is remnant of hydrovac activity.

Caerus D09A Pad
API 045 17758
Spill/Release Point ID #454721 (Flowline Spill)



Pipeline corridor to the north



Pipeline corridor, looking south.