

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2018

Submitted Date:

04/24/2018

Document Number:

689300960

FIELD INSPECTION FORM

Loc ID 335157 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

28 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnreenergy.com	Sr. Production Foreman
Ghan, Scott	970-744-8128	sghan@vnreenergy.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292114	WELL	PR	05/20/2008	GW	045-14600	SPECIALTY 34A-21-692	PR
292945	WELL	PR	05/27/2008	GW	045-14819	SPECIALTY 34C-21-692	PR
292946	WELL	PR	05/23/2008	GW	045-14820	SPECIALTY 33C-21-692	PR
292947	WELL	PR	05/30/2008	GW	045-14821	SPECIALTY 44C-21-692	PR
292948	WELL	PR	08/11/2008	GW	045-14822	SPECIALTY 43A-21-692	PR
292949	WELL	PR	08/10/2008	GW	045-14823	SPECIALTY 43C-21-692	PR
292950	WELL	PR	07/31/2008	GW	045-14824	SPECIALTY 44A-21-692	PR
292951	WELL	PR	05/25/2008	GW	045-14825	SPECIALTY 33A-21-692	PR

General Comment:

[Routine Field inspection](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Missing/ Torn Tank sign		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	1-800-921-8252		
Corrective Action:			Date:
Good Housekeeping:			
Type	OTHER		
Comment:	Staining in Tank Containment		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Hog panel fencing		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Livestock Panels		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 16		corrective date
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 9		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical units at Wellheads		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	500 BBLs	HEATED STEEL AST		,
Comment:	Centralized Battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	7	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:					
Yes/No	YES				
Comment:	Bradenhead valves open				
Corrective Action:				Date:	

Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	292114	Type:	WELL	API Number:	045-14600	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
BradenHead									
Comment:	Venting								
Corrective Action:					Date:				
Facility ID:	292945	Type:	WELL	API Number:	045-14819	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
BradenHead									
Comment:	Venting								
Corrective Action:					Date:				
Facility ID:	292946	Type:	WELL	API Number:	045-14820	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
BradenHead									
Comment:	Venting								
Corrective Action:					Date:				
Facility ID:	292947	Type:	WELL	API Number:	045-14821	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
BradenHead									
Comment:	Venting								
Corrective Action:					Date:				
Facility ID:	292948	Type:	WELL	API Number:	045-14822	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				

BradenHead		
Comment: <input type="text" value="Venting"/>		
Corrective Action: <input type="text"/>		Date: <input type="text"/>

Facility ID: 292949 Type: WELL API Number: 045-14823 Status: PR Insp. Status: PR

Producing Well		
Comment: <input type="text" value="Well Producing on plunger lift"/>		
Corrective Action: <input type="text"/>		Date: <input type="text"/>

BradenHead		
Comment: <input type="text" value="Venting"/>		
Corrective Action: <input type="text"/>		Date: <input type="text"/>

Facility ID: 292950 Type: WELL API Number: 045-14824 Status: PR Insp. Status: PR

Producing Well		
Comment: <input type="text" value="Well Producing on plunger lift"/>		
Corrective Action: <input type="text"/>		Date: <input type="text"/>

BradenHead		
Comment: <input type="text" value="Venting"/>		
Corrective Action: <input type="text"/>		Date: <input type="text"/>

Facility ID: 292951 Type: WELL API Number: 045-14825 Status: PR Insp. Status: PR

Producing Well		
Comment: <input type="text" value="Well Producing on plunger lift"/>		
Corrective Action: <input type="text"/>		Date: <input type="text"/>

BradenHead		
Comment: <input type="text" value="Venting"/>		
Corrective Action: <input type="text"/>		Date: <input type="text"/>

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Slope Roughening	Pass					
Berms	Pass					
		Gravel	Pass			
		Ditches	Pass			
		Compaction	Pass			
Seeding	Pass					

Comment: [Rutted location](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689300961	DocNum: 689300960.4/24/18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4444212