

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/23/2018

Submitted Date:

04/24/2018

Document Number:

685100474**FIELD INSPECTION FORM**
 Loc ID 316739 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 52530Name of Operator: MAGPIE OPERATING, INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Status Summary:**☒ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
warner, ryan	(970) 669-6308	magpieoil@yahoo.com	
Fischer, Alex		alex.fischer@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Burger, Craig		craig.burger@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232482	WELL	PR	03/01/2017	OW	107-05048	RICHFIELD-WIRICK-FEDERAL 1	EI

General Comment:

On 4/23/2018 COGCC Environmental Staff, Kris Neidel inspected the Richfield-Wirick-Federal #1. Weather was sunny and 55 deg, ground was damp from rain and snowmelt. This inspection is a follow up to an Inspection dated 3/30/2018. It is Magpies responsibility to assure that corrective actions from previous inspection have been addressed. COGCC staff witnessed pooling of water at the wellhead. Surface water flow is directed around the well, surface water is ~20' from wellhead. The Tank Battery secondary containment volume that was mentioned in previous inspection should be evaluated. It is not obvious due to vegetation if the tanks have adequate secondary containment, this should be addressed immediately. By 3/23/2018, an eForm 19, Spill/Release report should be filed with COGCC documenting spill that was discovered on 3/30/2018 and address fluid that was observed around the well on 4/23/2018. Photos are attached. Bubbles were observed coming from the outside of the casing, Contact COGCC Engineering Supervisor, Craig Burger at 970-625-2497 regarding integrity issues.

Inspected FacilitiesFacility ID: 232482 Type: WELL API Number: 107-05048 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100477	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4444245