

GOLDEN EAGLE MINE GE-71-93 API# 05-071-06455 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 23, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102769



PHOTO 1: OVERVIEW OF LOCATION TO NORTHWEST

GOLDEN EAGLE MINE GE-71-93 API# 05-071-06455 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 23, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102769



PHOTO 2: THE GRAVEL ON THE WELL PAD WAS REMOVED. THE EARTH DISTURBANCE WAS HYDRO-SEEDED WITH AN APPROVED HILL RANCH SEED MIX TO PROMOTE THE ESTABLISHMENT OF VEGETATION.

GOLDEN EAGLE MINE GE-71-93 API# 05-071-06455 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 23, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102769



PHOTO 3: THE GRAVEL ON THE WELL PAD WAS REMOVED. SOIL WAS DELIVERED TO RECONTOUR THE PAD WHERE THE GRAVEL WAS REMOVED. THE EARTH DISTURBANCE WAS HYDRO-SEEDED WITH AN APPROVED HILL RANCH SEED MIX TO PROMOTE THE ESTABLISHMENT OF VEGETATION.

GOLDEN EAGLE MINE GE-71-93 API# 05-071-06455 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 23, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102769



PHOTO 4: LOCATION WHERE STORMWATER DISCHARGES INTO RAVINE. THIS AREA ON THE SOUTHWEST CORNER OF THE PAD WAS SWELLED OUT TO RECEIVE RUN OFF FROM THE ACCESS ROAD AS SHEET FLOW.

GOLDEN EAGLE MINE GE-71-93 API# 05-071-06455 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 23, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102769



PHOTO 5: LOCATION WHERE STORMWATER DISCHARGES INTO RAVINE. THIS AREA ON THE SOUTHWEST CORNER OF THE PAD WAS ARMORED FOR LONG TERM EROSION CONTROL.

GOLDEN EAGLE MINE GE-71-93 API# 05-071-06455 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 23, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102769



PHOTO 6: SITE FACING EAST, ADJACENT TO THE LEASE ROAD.