

Inspection Photos  
Location Name: Rouse USX A #5-17  
Location: 306455



Photo from prior inspection for comparison (arrow emphasis on damaged sign)

Photo 1: Wellhead, looking SW. Sign repaired.