

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2018

Submitted Date:

04/26/2018

Document Number:

690100482

FIELD INSPECTION FORM

Loc ID 318502 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: K P KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Jacobson, Eric		eric.jacobson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241423	WELL	PR	03/20/1995	GW	123-09212	UPRR 42 PAN AM AN 1	EG

General Comment:

COGCC Engineering Integrity staff is waiting on the final submittal of flowline NTO data for this well (submittal of satisfactory flowline pressure test completed). Details in the flowline section of this report. Photos uploaded can be accessed via link at end of report.

Inspected Facilities

Facility ID: 241423 Type: WELL API Number: 123-09212 Status: PR Insp. Status: EG

Flowline

#1	Type: Non-Well Site	1 of Lines
----	---------------------	------------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents: Multiphase

Integrity Summary

Failures: Spills: Repairs Made: No
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Fail Charted:

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Based on communications between KPK and COGCC Engineering Integrity staff (email date 3/14/18), the offsite/ wellhead flowline has failed a recent pressure test (flowline pressure test date 3/08/18). The well is currently shut in (at wellhead)

 Note: As soon as possible, provide COGCC Integrity staff with a tentative schedule for 1) Identifying the point(s) of failure on the flowline 2) repairing flowline or abandoning/ replacing the flowline 3) completing post repair flowline pressure testing.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100487	Signage and wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4445933
690100488	Flowline shut in	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4445934