

# Inspection Photos

API: 05-067-08171

Operator: HILCORP ENERGY COMPANY

Inspection Date: 4/12/2018



**Photo 1. View of the project area from the southeastern corner facing center.**



**Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is progressing, largely with western wheatgrass (*Pascopyrum smithii*), crested wheatgrass (*Agropyron cristatum*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).**



**Photo 3. View of the western portion of the project area from the southern portion facing northwestward.**



**Photo 4. View of wattles on the eastern edge of the working area. This is a temporary stormwater control and will need careful monitoring and maintenance as needed.**



**Photo 5. View of area in eastern project area with exposed soils, appears to be disturbed for erosion control and needs re-seeding/stabilization measures.**



**Photo 6. View of wattles in the northeastern edge of the project area that are full of sediment and need maintenance.**



**Photo 7. View of an example of portion of liner material in project area. Several of these are present on the well pad and within the interim reclamation area.**