

# Inspection Photos

API: 05-067-08640

Operator: HILCORP ENERGY COMPANY

Inspection Date: 4/12/2018



**Photo 1. View of the project area from the southwestern corner facing center.**







**Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation is progressing, largely with western wheatgrass (*Pascopyrum smithii*), crested wheatgrass (*Agropyron cristatum*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).**





**Photo 3. View of the western portion of the project area from the southwestern portion facing northward.**





**Photo 4. View of unmarked rig anchor within the interim reclamation area.**





**Photo 5. View of another unmarked rig anchor within the project area.**





**Photo 6. View of wood debris within the interim reclamation area. Wood, liner debris, and small pieces of trash observed throughout the project area.**





**Photo 7. View of head-cut and erosional channel forming within the northeastern portion of the project area.**





**Photo 8. View of head-cut and erosional channel forming along the access road, up to 1.5 feet deep.**