

GOLDEN EAGLE MINE NW-3-6-95 API# 05-071-06405 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 26, 2018  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102757



PHOTO 1 : GOLDEN EAGLE MINE NW-3-6-95 RECLAMATION FACING NORTH. THE WELL PAD WAS RECONTOURED TO MATCH THE SURROUNDING TERRAIN. GRADING TECHNIQUES WERE INSTALLED ON THE CONTOUR TO PROMOTE GROUND INFILTRATION AND PREPARE THE SOIL FOR SEEDING. THE EARTH DISTURBANCE WAS STABILIZED BY HYDRO-SEEDING USING AN APPROVED HILL RANCH SEED MIX TO PROMOTE THE ESTABLISHMENT OF VEGETATION. THE TOP SOIL STOCKPILE WAS UTILIZED DURING RECLAMATION ACTIVITIES. (2) WATER BARS WERE INSTALL TO REDUCE RUN OFF VELOCITY. A DIRT BERM WAS INSTALLED DOWN GRADIENT OF THE PROJECT TO PROVIDE PERIMETER SEDIMENT CONTROL.

GOLDEN EAGLE MINE NW-3-6-95 API# 05-071-06405 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 26, 2018  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102757



PHOTO 2 : GOLDEN EAGLE MINE NW-3-6-95 RECLAMATION FACING SOUTHEAST.

GOLDEN EAGLE MINE NW-3-6-95 API# 05-071-06405 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 26, 2018  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102757



GRADING  
TECHNIQUES

PHOTO 3 : GOLDEN EAGLE MINE NW-3-6-95 RECLAMATION FACING EAST.

GOLDEN EAGLE MINE NW-3-6-95 API# 05-071-06405 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 26, 2018  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102757




PHOTO 4 : GOLDEN EAGLE MINE NW-3-6-95 RECLAMATION FACING WEST. VIEW OF RECLAIMED FILL SLOPE.

GOLDEN EAGLE MINE NW-3-6-95 API# 05-071-06405 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 26, 2018  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102757



PHOTO 5 : GOLDEN EAGLE MINE NW-3-6-95 RECLAMATION FACING SOUTH.