

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2018

Submitted Date:

04/27/2018

Document Number:

679700852**FIELD INSPECTION FORM**

Loc ID 317697 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1801 BROADWAY #500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
GWOC Inspections		cogccinspections@gwogco.com	
COGCC Enforcement		dnr_cogccenforcement@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239808	WELL	PR	01/01/2018	OW	123-07596	PIERCE UNIT 2	EI
454672	SPILL OR RELEASE	AC			-	Pierce Unit 2 flowline	EI

**General Comment:**

This is a followup inspection to Inspection #679700835. Late spill reporting documented on inspection #679700835 will be referred for enforcement.

Inspected Facilities									
Facility ID:	239808	Type:	WELL	API Number:	123-07596	Status:	PR	Insp. Status:	EI
Facility ID:	454672	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

**Environmental****Spill/Remediation:**

**Comment:** COGCC followup inspection to #679700835 and spill ID#454672. Excavation remains open and evidence of petroleum impacted soil remains in sidewalls and base of excavation. Oily stockpile had been removed and pipeline has been repaired. It does not appear the excavation is materially larger than was observed on the 3/30/2018 site visit. During site visit, Operator stating that one additional soil sample collected from 11 feet below ground from a pothole in the base of the excavation contained a TPH concentration of approximately 1200 mg/kg. Operator stated their plan to advance soil borings to define the extent of impacts prior to additional excavation.

**Corrective Action:** Submit a Form 27 by May 4, 2018. The Form 27 shall include: a detailed plan for proposed additional site investigations, a description of remediation plans, all soil analytical data with site diagram showing sample locations for soil samples collected to date. Form 27 shall also include proposed dates to complete further investigation, excavation or remediation, and commencement of surface reclamation. Provide 48 hours notice of all future fieldwork to COGCC and to Surface Owner.

**Date:** 05/04/2018

**Emission Control Burner (ECB):** \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Pilot:** \_\_\_\_\_ **Wildlife Protection Devices (fired vessels):** \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700853	Pierce Unit 2 flowline excavation photos 4-27-2018	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4447766">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4447766</a>