

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2018

Submitted Date:

04/27/2018

Document Number:

684905369

**FIELD INSPECTION FORM**

Loc ID 331089 Inspector Name: Pesicka, Conor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1775 SHERMAN STREET - STE 3000  
City: DENVER State: CO Zip: 80203

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258320	WELL	PR	01/01/2014	OW	123-20136	STATE 5519 21-8	PA

**General Comment:**

Inspection PA per form 42 doc#401288392 . Little sign of regrowth on location. Port-a-john on location, see housekeeping.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type: UNUSED EQUIPMENT

Comment: Unused port-a-john S of location

Corrective Action: Comply with rule 603.f.

Date: 07/27/2018

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	corrective date
Emission Control Device	# 0	
Comment: removed		
Corrective Action:		Date:
Gas Meter Run	# 0	
Comment: removed		
Corrective Action:		Date:
Plunger Lift	# 0	
Comment: removed		
Corrective Action:		Date:
Plunger Lift	# 0	
Comment: removed		
Corrective Action:		Date:

Comment: removed

Corrective Action:

Date:

Type: Gas Meter Run # 0

Comment: removed

Corrective Action:

Date:

Type: Plunger Lift # 0

Comment: removed

Corrective Action:

Date:

Type: Plunger Lift # 0

Comment: removed

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				
Comment: removed					
Corrective Action:					Date:

Comment: removed

Corrective Action:

Date:

**Paint**

Condition:

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				
Comment: removed					
Corrective Action:				Date:	
<b>Paint</b>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
<b>Venting:</b>					
Yes/No					
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 258320 Type: WELL API Number: 123-20136 Status: PR Insp. Status: PA

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
684905370	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4448224">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4448224</a>