

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/18/2018

Submitted Date:

04/30/2018

Document Number:

679904306**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 324793      Welsh, Brian      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 16520Name of Operator: CHEMCO INCAddress: 6970 SOUTH HOLLY CIR STE 206City: CENTENNIAL      State: CO      Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone        | Email                   | Comment |
|--------------|--------------|-------------------------|---------|
| Neher, Gray  | 303-771-7777 | bogray@msn.com          |         |
| Quint, Craig |              | craig.quint@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 212645      | WELL | IJ     | 11/07/2014  | DSPW       | 061-06005 | LINCOLN 1     | AC          |

**General Comment:**5 Year UIC MIT

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Dirt road through pasture |       |  |
| Corrective Action  | L                         | Date: |  |

Overall Good: ☒

|                      |   |       |  |
|----------------------|---|-------|--|
| <b>Signs/Marker:</b> |   |       |  |
| Type                 | WELLHEAD                                |       |  |
| Comment:             | Lease sign mounted to fence at wellhead |       |  |
| Corrective Action:   |   | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |                              |       |  |
|--------------------|------------------------------|-------|--|
| <b>Fencing/:</b>   |                              |       |  |
| Type               | WELLHEAD                     |       |  |
| Comment:           | Metal panels around wellhead |       |  |
| Corrective Action: |                              | Date: |  |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 212645 Type: WELL API Number: 061-06005 Status: IJ Insp. Status: AC**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

|            |   |                              |                             |
|------------|---|------------------------------|-----------------------------|
| Inj./Tube: | Pressure or inches of Hg _____<br>(e.g. 30 psig or -30" Hg) | Previous Test Pressure _____ | MPP _____                   |
| TC:        | Pressure or inches of Hg _____                              | Previous Test Pressure _____ | Inj Zone: <u>MSSP</u>       |
| Brhd:      | Pressure or inches of Hg _____                              | Previous Test Pressure _____ | Last MIT: <u>04/18/2013</u> |
|            |   |                              | AnnMTReq: <u>NO</u>         |

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: 5 Year Tbg psi: -15" HG Csg psi: 0 PSIG BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: INITIAL CASING WAS DEAD. RIG UP NITROGEN. PRESSURE UP CSG TO 300 PSIG.  
5-MIN 300#. 10-MIN 300#. 15-MIN 300#. 0 PSI LOSS

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment: [Location is partially grassed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 679904334    | Form 21     | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4448990">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4448990</a> |