

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2018

Submitted Date:

04/30/2018

Document Number:

689701299**FIELD INSPECTION FORM**Loc ID 446582 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446575	WELL	DG	09/15/2017	GW	045-23264	BMC D 41C-18-07-95	WK
446588	WELL	WO	09/14/2017	GW	045-23276	BMC D 31C-18-07-95	WK
446765	WELL	WO	09/10/2017	GW	045-23278	BMC D 41B-18-07-95	WK
447701	WELL	WO	09/12/2017	GW	045-23313	BMC D 21C-18-07-95	WK

General Comment:[Inspection is in response to an odor complainant received by CDPHE.](#)

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 855-625-9922

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 446582 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: The flow back operations being performed at the location are a green complete style.

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 446575 Type: WELL API Number: 045-23264 Status: DG Insp. Status: WK**Completion**Operation: FlowbackDate Flowback: 04/25/2018Contractor: LEC Services

Comment: The flow back operations being performed at the location are a green complete style. This kind of flow back consists of a Primary or high stage. This vessel does most of the work in the flow back operation, separating the oil, gas and water. Gas is sent to sales. The water is then shipped to a secondary vessel, or low stage, where the final breakout of gas occurs. The gas is then flared off via the portable combustor. The water is then shipped to the flow back tanks and reused for the Frac operations after being chemically treated. The location also has a system in place that pulls a vacuum from the 6 flow back tanks and adds an odor control scent before being released to atmosphere.

Corrective Action:

Date:

Facility ID: 446588 Type: WELL API Number: 045-23276 Status: WO Insp. Status: WK**Completion**Operation: FlowbackDate Flowback: 04/25/2018Contractor: LEC ServicesComment:

Corrective Action:

Date:

Facility ID: 446765 Type: WELL API Number: 045-23278 Status: WO Insp. Status: WK**Completion**Operation: FlowbackDate Flowback: 04/25/2018Contractor: LEC ServicesComment:

Corrective Action:

Date:

Facility ID: 447701 Type: WELL API Number: 045-23313 Status: WO Insp. Status: WK**Completion**Operation: FlowbackDate Flowback: 04/25/2018Contractor: LEC ServicesComment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
		Check Dams	Pass			
		Compaction	Pass			
		Gravel	Pass			
Hydro Mulch	Pass					
Berms	Pass					
				Material Handling And Spill Prevention		Duck pond style containment under frac equipment.
Check Dams	Pass					
Ditches	Pass					
Rip Rap	Pass					
Waddles	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689701309	Inspection 689701299 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4449027