

Construction and Stormwater Inspection

April 25, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 454520

Inspection Document #: 682403512

Weld County, CO

SWSE Section 8 T1N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ENGLISH FARMS /8-10HZ
Location ID: 454520



Photo 1. Photo taken from the entrance of the location, facing North. Operator has failed to install a vehicle tracking device to prevent track of material offsite.



Photo 2. Photo taken from the entrance of the location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: ENGLISH FARMS /8-10HZ
Location ID: 454520



Photo 3. Photo taken from the eastern perimeter of the location, facing North. Ditch and berm BMP has been installed along the entire perimeter of the location. Portions of the berm do not appear to be stabilized. An unconsolidated berm BMP is not a proper functioning BMP. Photo also illustrates ditch BMP filling up with fines from unconsolidated soil material from the well pad. Appears topsoil is being stored along the northeastern and southwestern perimeter of the location.

Photo 4. Photo taken from the northeast perimeter of the location, facing West. See comments under Photo 3.

Inspection Photos
Location Name: ENGLISH FARMS /8-10HZ
Location ID: 454520



Photo 5. Photo taken from the northwest perimeter of the location, facing South. See comments under Photo 3.



Photo 6. Photo taken from the southwest perimeter of the location, facing East. See comments under Photo 3.

Inspection Photos
Location Name: ENGLISH FARMS /8-10HZ
Location ID: 454520



Photo 7. Photo taken from the southern perimeter of the location, facing North. Sediment trap is in-process of being constructed.