

Inspection Photo
Dunn 16
API# 045-07041
Inspection # 689301002



Location photo # 1




Location photo # 2 stained material in tank battery

Inspection Photo
Dunn 16
API# 045-07041
Inspection # 689301002



Location photo # 3 Stained material



Location photo # 4, Stained material in tank battery, leaking valve

Inspection Photo
Dunn 16
API# 045-07041
Inspection # 689301002



Location photo # 5 storm water issue behind separator

Location photo # 6, Storm water issue

Inspection Photo
Dunn 16
API# 045-07041
Inspection # 689301002



**Location photo # 7, Storm water issue,
looking East towards the vessel**

Location photo # 8, Storm water issue



**Inspection Photo
Dunn 16
API# 045-07041
Inspection # 689301002**



Location photo # 9 storm water issue behind separator

Location photo # 10