

Inspection Photos
Location Name: Brantner 30-9
Location ID: 323643



Wellhead



Location

Inspection Photos
Location Name: Brantner 30-9
Location ID: 323643




Produced Water Tank Corrective Action: Equipment not anchored or inadequately anchored



Separator, Corrective Action: Equipment not anchored or inadequately anchored

Inspection Photos
Location Name: Brantner 30-9
Location ID: 323643



Floodplain Map

