

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Red iron

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date: _____

Type: Horizontal Heated Separator # 1

Comment: Vessel is not anchored per rule 603.h.(2)B. See photos.

Corrective Action: Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.

Date: 05/31/2018

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date: _____

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date: _____

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: _____

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment: Shares berms with produced water tank.						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST			
Comment: Tank is not anchored per rule 603.h.(2)B. See photos.						
Corrective Action: Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.					Date: 05/31/2018	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment: SHares berms with production tank.						
Corrective Action:					Date:	
Venting:						
Yes/No						
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 245515 Type: WELL API Number: 123-13310 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 435349 Type: TANK API Number: - Status: AC Insp. Status: AC

Producing Well

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<u>Well and battery are located in FEMA floodplain.</u>	<u>kraicha</u>	<u>05/01/2018</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
<u>691300149</u>	<u>Inspection Photos</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4450938</u>