

Inspection Photos 04/27/18
Location: KP Kauffman Paul Heinze #1
API # 05-123-08382



Signage and view toward excavation (looking NW)



View of excavation and flowline repair work in progress
Looking North

Inspection Photos 04/27/18
Location: KP Kauffman Paul Heinze #1
API # 05-123-08382



View of flowline repair in progress; area where poly has been stung (slip lined) in to existing pipe (w tracer wire)



View of flowline repair; in area of well tie in and installation of riser/ valve set

Inspection Photos 04/27/18
Location: KP Kauffman Paul Heinze #1
API # 05-123-08382



Photo of buried vessel removed from excavation; lacking integrity with obvious corrosion holes



View of pump jack/ wellhead