

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2018

Submitted Date:

05/02/2018

Document Number:

690100505

**FIELD INSPECTION FORM**

Loc ID 317642 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1775 SHERMAN STREET - STE 3000  
City: DENVER State: CO Zip: 80203

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239674	WELL	SI	01/01/2017	GW	123-07462	WALSH 1	EG

**General Comment:**

Engineering Integrity Inspection performed on May 1st, 2018 in response to initial form 19 spill report Doc #401623323 received by COGCC on 04/27/2018 that outlines: PDC discovered a reportable historical spill at the Walsh 1 while abandoning the battery. Current recovery efforts are mitigating impacts. Details of observations made during this field inspection are available in the flowline/ comment sections of this report. Photos uploaded can be accessed via link(s) at end of report.

**Inspected Facilities**

Facility ID: 239674 Type: WELL API Number: 123-07462 Status: SI Insp. Status: EG

**Flowline**

#1	Type:	of Lines
<u>Flowline Description</u>		
Flowline Type:	Size:	Material:
Variance:	Age:	Contents:
<u>Integrity Summary</u>		
Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:
<u>Pressure Testing</u>		
Witnessed:	Test Result:	Charted:
<u>COGCC Rules(check all that apply)</u>		
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment		
Comment:	Notice of flowlines abandoned form 42 doc #401370246 received on 08/09/2017. There were No flowline risers observed at this location.	
Corrective Action:		Date:

**COGCC Comments**

Comment	User	Date
Well has been plugged and abandoned; COGCC form 42 notice of start of plugging operations doc#401593007 filed on 03/30/2018.	maclarej	05/02/2018
Note: There is a disconnected/ fenced out of service gas gathering riser and meter run on the North side of location.	maclarej	05/02/2018
COGCC Rule 1004. FINAL RECLAMATION OF WELL SITES AND ASSOCIATED PRODUCTION FACILITIES (partial description of rule) a. Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100507	Signage at access road	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4451554">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4451554</a>
690100508	Location and area of release fenced (view east)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4451555">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4451555</a>
690100509	Disconnected gas meter run (fenced/ view NW)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4451556">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4451556</a>