

Inspection Photos 4/27 – 5/1 2018
Location: 8 North LLC Dawson 2-10
API # 05-013-06087 Location ID #446622



Location signage and view of phase 1 remediation area on location. Flowlines are exposed in the excavation (view East)
Note: Photo taken 4/27/18



Closer view of excavated area exposing both active dump lines and (previously unknown) historically abandoned flowlines (view to East)
Note: Photo taken 4/27/18

Inspection Photos 4/27 – 5/1 2018
Location: 8 North LLC Dawson 2-10
API # 05-013-06087 Location ID #446622



Closer view of flowlines exposed in excavation; The short valved/ plugged line is the active Crude Oil dump flowline (isolated during remediation); and (4) historically abandoned flowlines. Note: Photo taken 4/27/18



Waddles surrounding soils stockpile and flowline pipe materials removed from excavated area.

Note: Photo taken 4/27/18

Inspection Photos 4/27 – 5/1 2018
Location: 8 North LLC Dawson 2-10
API # 05-013-06087 Location ID #446622



**Close up view of flowlines exposed in excavation; (1) Valved/
plugged (FBE coated) active flowline; (4) historically
abandoned flowlines were discovered while excavating.**

Note: Photo taken while on site 4/24/18



Photo of shut in wellhead (Locked out/ Tagged out)

Note: Photo taken while on site 4/24/18

Inspection Photos 4/27 – 5/1 2018
Location: 8 North LLC Dawson 2-10
API # 05-013-06087 Location ID #446622



View of (4) historically abandoned flowlines discovered while excavating; in process of being removed

Note: Photo taken while on site 5/01/18



Corrosion holes observed in sections of the historically abandoned flowlines.

Note: Photo taken while on site 5/01/18