

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2018

Submitted Date:

04/26/2018

Document Number:

691400227**FIELD INSPECTION FORM**
 Loc ID 331136 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email                                | Comment                         |
|--------------|-------|--------------------------------------|---------------------------------|
| Precup, Jim  |       | james.precup@state.co.us             |                                 |
| ,            |       | Cogcc.inspections@crestone<br>pr.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 258757      | WELL | PR     | 02/01/2018  | GW         | 123-20211 | ECHEVERRIA 12-2 | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | WELLHEAD     |       |  |
| Comment:           | Adequate     |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           | Adequate     |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           | Adequate     |       |  |
| Corrective Action: |              | Date: |  |

|                       |                              |       |                 |
|-----------------------|------------------------------|-------|-----------------|
| <b>Equipment:</b>     |                              |       | corrective date |
| Type: Gathering Line  | # 1                          |       |                 |
| Comment:              |                              |       |                 |
| Corrective Action:    |                              | Date: |                 |
| Type: Gas Meter Run   | # 1                          |       |                 |
| Comment:              | No calibration log on sight. |       |                 |
| Corrective Action:    | Measure gas per Rule 329.    | Date: | 05/26/2018      |
| Type: Bird Protectors | # 3                          |       |                 |

|                                 |     |       |  |
|---------------------------------|-----|-------|--|
| Comment:                        |     | Date: |  |
| Corrective Action:              |     | Date: |  |
| Type: Plunger Lift              | # 2 |       |  |
| Comment:                        |     | Date: |  |
| Corrective Action:              |     | Date: |  |
| Type: Emission Control Device   | # 1 |       |  |
| Comment:                        |     | Date: |  |
| Corrective Action:              |     | Date: |  |
| Type: Horizontal Heater Treater | # 2 |       |  |
| Comment:                        |     | Date: |  |
| Corrective Action:              |     | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CONDENSATE         | 1 | 300 BBLs | STEEL AST |         | 40.170600,-104.862550 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------|---------|--------|
| PRODUCED WATER     | 1 | OTHER    |      |         | ,      |
| Comment:           |   |          |      |         |        |
| Corrective Action: |   |          |      |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) | 110 BBL  |
| Other (Type)     |          |

**Berms**

| Type               | Capacity                          | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-----------------------------------|---------------------|---------------------|-------------|
|                    |                                   |                     |                     |             |
| Comment:           | Shares berm with condensate tank. |                     |                     |             |
| Corrective Action: |                                   |                     |                     | Date:       |



| Inspected Facilities |        |                    |      |             |           |         |    |               |    |
|----------------------|--------|--------------------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 258757 | Type:              | WELL | API Number: | 123-20211 | Status: | PR | Insp. Status: | PR |
| Producing Well       |        |                    |      |             |           |         |    |               |    |
| Comment:             |        | PR                 |      |             |           |         |    |               |    |
| Corrective Action:   |        |                    |      |             |           |         |    | Date:         |    |
| BradenHead           |        |                    |      |             |           |         |    |               |    |
| Comment:             |        | Plumbed to surface |      |             |           |         |    |               |    |
| Corrective Action:   |        |                    |      |             |           |         |    | Date:         |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401622108    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4446701">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4446701</a> |
| 691400228    | LOC PICS             | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4446693">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4446693</a> |