

Inspection Photos

05/3/2018

Operator: WIEPKING-FULLERTON ENERGY LLC -
96340

Location ID: 436579

Inspection Doc. Number: 682503291
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 436579



Photo 1: Photo taken from the southeast end of the constructions site, facing north. Photo shows construction activities in process, however, no stormwater and sediment control BMPs have been installed.



Photo 2: Photo taken from the southeast end of the constructions site, facing west. Photo shows construction activities in process, however, no stormwater and sediment control BMPs have been installed.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 436579



Photo 3: Photo taken from the southwest end of the constructions site, facing north. Photo shows construction activities in process, however, no stormwater and sediment control BMPs have been installed.



Photo 4: Photo taken from the southwest end of the constructions site, facing east. Photo shows construction activities in process, however, no stormwater and sediment control BMPs have been installed.

Inspection Photos

Operator: WIEPKING-FULLERTON ENERGY LLC - 96340

Location ID: 436579



Photo 5: Photo taken from the northwest end of the construction site, facing south. Photo shows construction activities in process, and the topsoil pile however, no stormwater and sediment control BMPs have been installed.



Photo 6: Photo taken from the northwest end of the construction site, facing east. Photo shows surface roughening has been installed on the northern perimeter of the location. Surface roughening alone is insufficient for a control.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 436579



Photo 7: Photo taken from the north end of the construction site, facing southeast. Photo shows construction activities in process, and the topsoil pile however, no stormwater and sediment control BMPs have been installed.



Photo 8: Photo taken from the north end of the construction site, facing southeast. Photo shows construction activities in process, and the topsoil pile however, no stormwater and sediment control BMPs have been installed.