

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2018

Submitted Date:

05/02/2018

Document Number:

689401190**FIELD INSPECTION FORM**Loc ID 312460 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10150Name of Operator: BLACK HILLS PLATEAU PRODUCTION LLCAddress: 1515 WYNKOOP ST STE 500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☒ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221666	WELL	PA	07/21/2014	GW	077-08268	FEDERAL (UTE WATER) 6-2	PA

General Comment:

Inspection in response to complaint Doc#200445784 . Any corrective actions not addressed from previous inspections are still applicable.

Inspected FacilitiesFacility ID: 221666 Type: WELL API Number: 077-08268 Status: PA Insp. Status: PA**Complaint**Comment: [FIU staff did follow up to initial inspection Doc#689401184 with FLIR camera to try and detect a possible source of odor.](#)

Corrective Action:

Date:

Completion

Operation:

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: None Speed: _____ (mph) Direction From: _____ Weather: Partly Temperature: 55 (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
11:00	AM	12:15	PM	Other

Comment: FLIR survey was around area of plugged well and adjacent pipeline that is near location. Well was plugged 7/21/14 see Form 6 (S) Doc#400757473. No evidence of leak or venting was observed at the time of the inspection.

Corrective
Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689401191	Federal 6-2 Follow up photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4453004