

Inspection Photos

05/04/2018

Operator: WIEPKING-FULLERTON ENERGY LLC -
96340

Location ID: 433577

Inspection Doc. Number: 682503301
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 433577



Photo 1: Photo taken from the southwest end of the location, facing south. Photo shows stormwater erosion degradation resulting in sediment transport from location onto the interim areas. 6 foot measuring stick for reference.



Photo 2: Photo taken from the southwest end of the location, facing south. Photo shows stormwater erosion degradation resulting in sediment transport from location onto the interim areas. 6 foot measuring stick for reference.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 433577



Photo 3: Photo taken from the southwest end of the location, facing north. Photo shows stormwater erosion degradation resulting in sediment transport from location and access road onto the interim areas.



Photo 4: Photo taken from the interim areas south of the location, facing north. Photo shows stormwater erosion degradation resulting in sediment transport from location onto the interim areas. 6 foot measuring stick for reference

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 433577



Photo 5: Photo taken from the interim areas south of the location, facing south. Photo shows stormwater erosion degradation resulting in sediment transport from location onto the interim areas. 6 foot measuring stick for reference




Photo 6: Photo taken from the south end of the location. Photo shows stabilization concerns on the the slopes of the well pad. Insufficient stormwater and sediment control BMPs in place.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 433577



Photo 7: Photo taken from the west end of the location, facing north. Photo shows stormwater erosion degradation resulting in sediment transport from the interim areas onto the location. 6 foot measuring stick for reference.



Photo 8: Photo taken from the interim areas on the northwest end of the location, facing south. Photo shows stormwater erosion degradation resulting in sediment transport from the interim areas onto the location.