

**Inspection Photo
Clough RWF 321-14
API# 045-14028
Inspection # 689301042**



Location photo # 1



Location photo #2

Inspection Photo
Clough RWF 321-14
API# 045-14028
Inspection # 689301042



Location photo # 1 Ditch erosion along the side of the road



Location photo #2 Ditch erosion along the side of the road

Inspection Photo
Clough RWF 321-14
API# 045-14028
Inspection # 689301042



Location photo # 1 Ditch erosion along the side of the road



Location photo #2 Erosion at out let of culvert

**Inspection Photo
Clough RWF 321-14
API# 045-14028
Inspection # 689301042**



Location photo # 1 Continued Erosion below culvert



Location photo #2 Culvert Erosion