

**Inspection Photo
Clough RWF 34-14
API# 045-08991
Inspection # 689301049**



Location photo # 1



Location photo #2, Ruttred location

**Inspection Photo
Clough RWF 34-14
API# 045-08991
Inspection # 689301049**



Location photo # 3 Ruttred location