

**Inspection Photos**  
**Location Name: Haley-Ray 611N61W / 21SWSW**  
**Location #: 305413**



**Photo #1**  
**Facing NW**  
**Animal burrows in berms have been filled**



**Photo #2**  
**Facing NW**  
**Unused fittings have been removed**

**Inspection Photos**  
**Location Name: Haley-Ray 611N61W / 21SWSW**  
**Location #: 305413**



**Photo #3**  
**Facing West**

**PBV – Fiberglass H2O tank capacity now shown**



**Photo #4**  
**Facing West**

**Severe erosion appears to have been mitigated**

**Inspection Photos**

**Location Name: Haley-Ray 611N61W / 21SWSW**

**Location #: 305413**



**Photo #5**

**Haley Ray 13-21 wellhead facing NW.  
Stained soil appears to have been mitigated.**

