

Location

Overall Good:

Signs/Marker:

	Type BATTERY		
Comment:	Battery sign no longer shows any P&A'd wells		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		40.427400,-104.846060
Comment:	3" load line on water vault now has cap/screen to prevent animal/avian ingress.				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	60 Bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 437292 Type: TANK API Number: - Status: AC Insp. Status: TA

COGCC Comments

Comment	User	Date
This follow-up inspection only focuses on the CA items from FIR Doc #691200058 & FIRR Doc #401629134.	evinsb	05/07/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200073	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4455252