

Inspection Photo
Miller 14D-6-691
API# 045-14098
Inspection # 689301065



Location photo # 1



Location photo #2

**Inspection Photo
Miller 14D-6-691
API# 045-14098
Inspection # 689301065**



Location photo # 3



Location photo # 4, Peeling Tank sign

Inspection Photo
Miller 14D-6-691
API# 045-14098
Inspection # 689301065



Location photo # 5, Sign not legible



Location photo #6, Stained rock in tank battery containment.

**Inspection Photo
Miller 14D-6-691
API# 045-14098
Inspection # 689301065**



**Location photo # 7, Stained rock in tank
battery containment**



**Location photo # 8, stained rock in tank
battery containment**

Inspection Photo
Miller 14D-6-691
API# 045-14098
Inspection # 689301065



Location photo # 9, oily residue on tanks



**Location photo # 10, stained rock in tank
battery containment**

Inspection Photo
Miller 14D-6-691
API# 045-14098
Inspection # 689301065



Location photo # 11, oily residue on tank



Location photo # 12, Oily residue on tank

Inspection Photo
Miller 14D-6-691
API# 045-14098
Inspection # 689301065



Location photo # 13, Faded sign on methanol tank

Inspection Photo
Miller 14D-6-691
API# 045-14098
Inspection # 689301065



Location photo # 14, Storm water issue on access road



Location photo # 15, Storm water issue on access road

Inspection Photo
Miller 14D-6-691
API# 045-14098
Inspection # 689301065



Location photo # 16, Storm water issue on access road



Location photo # 17, Storm water issue on access road

Inspection Photo
Miller 14D-6-691
API# 045-14098
Inspection # 689301065



Location photo # 18, Storm water issue on access road



Location photo # 19, Storm water issue on access road