

# Inspection Photos

API: 05-083-06728

Operator: KINDER MORGAN CO2 CO LP

Inspection Date: 4/18/2018



**Photo 1. View of the project area from the northeastern corner facing center.**



**Photo 2. View of the edge of the project area from the northeastern corner facing southward. Vegetation removal is occurring and berms are being constructed. Per communication with onsite management, berm compaction will be completed this day.**



**Photo 3. View of the northern portion of the project area from the northeastern portion facing westward.**



**Photo 4. View of wattles in the eastern project area. Wattles should be placed outside of disturbed soils to prevent runoff.**



**Photo 5. View of the southeastern edge of the project area. Berms are properly compacted here. Vegetation on the well pad is in process of removal.**



**Photo 6. View of the western edge of the project area facing northward.**