

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/23/2018

Submitted Date:

05/03/2018

Document Number:

689500751

FIELD INSPECTION FORM

Loc ID 335758 Inspector Name: GRANAHAN, KYLE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 1125 ESCALANTE DR
City: RANGELY State: CO Zip: 81648

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Bleil, Rob	970-290-2912	rbleil@utahgascorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230304	WELL	PR	10/01/1993	GW	103-07964	STEELE B 7412	PR

General Comment:

[On location to conduct routine inspection](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Present/complete		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Present/complete		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:

Type:		#		corrective date
Bird Protectors		# 1		
Comment:				
Corrective Action:				Date:
Deadman # & Marked		# 4		
Comment:				
Corrective Action:				Date:
Horizontal Heated Separator		# 1		
Comment:				
Corrective Action:				Date:
Plunger Lift		# 1		
Comment:				
Corrective Action:				Date:
Gas Meter Run		# 1		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<50 BBLs	Open Top		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 230304 Type: WELL API Number: 103-07964 Status: PR Insp. Status: PR

Producing Well

Comment: PR via plunger lift, no leaks/venting present at time of inspection. No cellar present.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Ditches	Pass			
Compaction	Pass					
		Compaction	Pass			

Comment: No sediment flow evident

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689500752	Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4455885