

# Inspection Photos

API: 05-083-06542

Operator: QEP

Inspection Date: 4/18/2018



**Photo 1. View of the project area from the southeastern corner facing center.**



**Photo 2. View of the eastern edge of the working area from the southeastern edge facing northward. Soil berm is removed.**



**Photo 3. View of the eastern portion of the interim reclamation area. Area is re-seeded in response to previous inspection. Revegetation and weeds need to be monitored in this area.**