

# Inspection Photos

API: 05-083-06575

Operator: QEP

Inspection Date: 4/18/2018



**Photo 1. View of the project area from the southwestern corner facing center.**



**Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing but largely weedy with cheatgrass (*Bromus tectorum*).**



**Photo 3. View of the northeastern portion of the project area from the eastern edge facing northward.**