

Inspection Photos

API: 05-083-06538

Operator: QEP

Inspection Date: 4/18/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern edge of the working area from the southwestern corner facing eastward.



Photo 3. View of the eastern portion of the project area from the southwestern corner facing northward.



Photo 4. View of musk thistles (*Carduus nutans*) within the southern interim reclamation area.



Photo 5. View of musk thistles along the access road.