

# Inspection Photos

API: 05-083-06722

Operator: QEP

Inspection Date: 4/18/2018



**Photo 1. View of the project area from the southwestern corner facing center.**



**Photo 2. View of the southern edge of the working area from the southwestern corner facing eastward. Interim reclamation is conducted and area contoured to match surrounding agricultural field.**



**Photo 3. View of the western portion of the project area from the southwestern corner facing northward. Western portion of project area is in process of being revegetated. Straw mulch and seedlings observed.**



**Photo 4. Another view of western interim reclamation area and straw wattles in shallow swale along the western edge of the project area. Appear to be functioning.**



**Photo 5. View of young seedlings observed within the newly planted areas.**