

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2018

Submitted Date:

05/10/2018

Document Number:

690100523**FIELD INSPECTION FORM**

Loc ID 319616 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:                     

**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		cogccinspection@pdce.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243781	WELL	PR	07/30/2010	OW	123-11573	L-H 1	EG

**General Comment:**

COGCC engineering integrity inspection (flowline only) performed as a followup to 2017 flowline NTO inspection doc #689300008 conducted on 07/21/2017. Details of this inspection are outlined in the equipment/ flowline section of this report. Photos uploaded.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

#

Comment:

ACTION REQUIRED COMPLETED from FIR Doc #689300008 that outlines: (1) 2" unknown/unused riser at wellhead. Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. PDC Energy received the attached inspection of the LH 1 facility on 7/21/2017. Email reply from operator received by COGCC Integrity Group on 7/25/17 that states; It appears that the "unknown/unused riser at wellhead" identified in the inspection is in fact a stand for wellhead automation.

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 243781 Type: WELL API Number: 123-11573 Status: PR Insp. Status: EG**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100524	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4459467">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4459467</a>